



Perspectives on Wind Turbine Safety

Dr. Nat Janke-Gilman Meridian Energy Ltd.

NZ Wind Energy Association 2 May 2018





Fatalities during Feb-July 2017

Date	Location	Event
2 Feb 2017	Ramnagar wind farm, India	Contractor electrocuted in substation
15 Mar 2017	Kilgallioch wind farm, Scotland	Contractor fell 5 m from yaw platform
27 Mar 2017	La Bufa wind farm, Mexico	Contractor fell 25 m from tower platform
29 Mar 2017	Whitelee wind farm, Scotland	Maintenance worker fell from nacelle to ground
31 Mar 2017	Rayala wind farm, India	Welding in turbine started a fire
18 Apr 2017	Deerfield wind farm, USA	Mobile crane contacted HV overhead line
3 May 2017	Jamnagar wind farm, India	Mobile crane contacted HV overhead line
8 May 2017	Esbjerg harbour, Denmark	Contractor pinned between blade and trailer
17 Jul 2017	Binhai North H2 (offshore), China	Fire in offshore substation, worker drowned

Fatalities during Feb-July 2017


Date	Event		
2 Feb 2017	Contractor electrocuted		
15 Mar 2017	Contractor fell		
27 Mar 2017	Contractor fell		
29 Mar 2017	Worker fell		
31 Mar 2017	Welding fire		
18 Apr 2017	Crane contacted HV		
3 May 2017	Crane contacted HV		
8 May 2017	Contractor pinned		
17 Jul 2017	Offshore substation fire		

Key findings:

- Mostly contractors
- Not all in-turbine (substation, cranes, etc)
- Fall protection not applied
- Lock Out procedures not applied
- Hot Work procedures not applied
- General violations of existing procedures
- Unplanned work



BATHTUB CURVE OF HUMAN ERROR



Death of an Elevator Technician



- Wellington-based technician for Otis elevators
- Crushed to death, 2016
- Coroner's inquest, 2018
- Pit switch not engaged (or tripped off)
- 27 years experience,
 Level 4 service tech





Evolution of a Safety Culture

Focus on systems

SUPPORT

SAFETY CULTURE

Stop counting errors

and attributing

blame!

Focus on technicians

> Fix the systems and manage the problems

the Techs

TRAIN

Teach away the errors

POLICE

the Techs

the Techs

"Safety-II" Punish the crimes

Our framework: Wind Turbine Safety Rules

To achieve Safety From The System:

- 1. all work in the turbine is **planned work**...
- 2. following an Approved Written Procedure...
- 3. which lists approved isolations and safety steps.

The primary goal is technician safety

JSA Job Safety Analysis

WSSP Worksite Safety Plan

AWP Approved Written Procedure (ROP) (or Routine Operating Procedure)

WI Work Instructions

JSA


WSSP

AWP (ROP)

WI

Job Safety Analysis

- About 30 generic JSAs
- Several individual task-based JSAs
- Hazards, Risks, and Control Measures



JSA

Worksite Safety Plan

Toolbox talk, before the job

WSSP

Summary of Hazards + Controls

AWP (ROP) List of related documentation

Emergency Rescue Plan

WI

Everyone signs on

JSA

WSSP

AWP (ROP)

WI

Worksite Safety Plan

TUK WSSP 704—Repla Te Uku—Siemens 2.3MW-1 V1.3—Created 2017-05-23-	101—Worksite Safet		TUK WSSP 704 V1.3	2/2	TUK WSSP 704—Replace Te Uku—Siemens 2.3MW-101 V1.3—Created 2017-05-23—
_	_			meridian	
	. ,	otor or yaw gea		- Inchaidh	Working at height Use safety harness and fall a
eplacement or major work on w section as required.	n yaw motors or yaw	gear, including application	on of yaw lock and entry to		Service lift Perform pre-use checks befo
	ine type:	Turbine #:	Date:		Objects falling from height • Keep clear of potential drop:
Te Uku Si	iemens 2.3MW-101				 Identify 15 m drop zone arou
k or work order #:		Associated permits:			Lifting operations Pre-use checks. Trained and
					Mobile plant and equipment
rk description:					Ensure good comms betwee Conduct pre-use checks. We
					Rotating plant, entanglement, Observe wind speed limits.
					Hub entry—Be aware of risk Yaw lock—Isolate power to
. Turbine Alerts (li		ve etvietie ve e\			 Yaw entry—Test E-stop in y
			Return TOC time:		in the yaw space, limited to v
Request Transfer of Conf Confirm turbine alerts.	troi. Note 100 time.	recept 100 une.	recent roo unic.		Do not touch or keep your hat Release stored hydraulic en
ist any safety-related alerts b	nelow or write NONE.	Asset shutdown time:	Asset restart time:		 Safety glasses are required Chemical hazards, spills
ote any isolations already in p	olace.				 Review SDS sheets for cher
					Fire hazards Sweep and clean up all con
					 Hot work permit + fire watch
					 Electrical Supplies Isolate and de-energize, Lo
					 Prescribed electrical work (Pi Maintenance of electrical ar
					 Connection or disconnectio Testing, certification, inspec
Task-Related Ha	zards and Co	ntrols			 Only trained and competent
dentify hazards that you may e	encounter or create, on	this day, in this turbine, for			 Arc Flash (turbine main break Where possible, operate ma
Reduce risk by applying effectiv		eliminate or minimize those	hazards.		Otherwise wear arc-rated Pl
Hazards and Control Assurances, SM-El permits	ols				 Work in 'At Risk Areas' (any sp. Rescue plan. Work in pairs.
If assurance received, ackir	nowledge isolations in	'Alerts' box above. Note asso	ciated permit number.		Confined Space Entry Confined space entry permit
Safety from the System • Follow Approved Written P	rocedure—Keen signa	ture checknoints up to date			Fault-related hazards
General PPE requirements		tare eneckpoints up to date.			Consider whether the type of Yaw error—If there is a yaw
 Required at all times: Helm Required as appropriate: 0 		arm and face protection.			
Rings, Jewellery, Watches, L Remove rings/jewellery/wa			ire they cannot cause harm		
through entanglement with	equipment or ladders,	or by contact with live electri			
 Tie back long hair and loos Daily/pre-use checks 	se clouning.				
 Check turbine log book, fire Public safety, farm operation 			ane/chain hoist, lifting gear.		C. Resources
 Site hazard boards. 'Whos 	OnLocation' hazard ale	erts. Daily/Weekly Meetings. E	Be aware of others on site.		List task-related safety resources
 Visitor inductions, Contracto Direct supervision required 			sessment TUK WI 002A.		General PPE, Working at H December 1 OTO agreement
Driving					 Personal LOTO equipment- First aid kit—Bring one first aid
Drive to the conditions. Par Noise	rk sately facing into the	wind. Pre-use safety check for	or your vehicle.		 Insulated and calibrated elect Gas monitor—Mandatory for of
Use nearing protection at t	turbine start/stop and as	appropriate (e.g. use of pow	ver tools).		Replacement kit for yaw gear
Manual handling, posture Use lifting aids. Plan team	lifts. Avoid poor posture	e. Perform periodic stretches.			
Trips, Slips and Falls Take care in and around the	ne work site. Clean up a	is you go.			:
anc care in and around a	to more one. Croull up a	, yo.			•

	K WSSP 704—Replace yaw motor or yaw gear	TUK WSSP 704				
	Uku—Siemens 2.3MW-101—Worksite Safety Plan .3—Created 2017-05-23—DRAFT	V1.3				
$\overline{}$						
Working at height Use safety harness and fall arrest system including slider, lanyards.						
П 5	Service lift					
	 Perform pre-use checks before use – Trained and competent personnel only to ope Diects falling from height 	rate service lift.				
	 Keep clear of potential drop zone. Use tool lanyards. Wear appropriate PPE. 					
	 Identify 15 m drop zone around turbine using cones/tape/signage, or other means. 					
	 ifting operations Pre-use checks. Trained and competent personnel only to operate crane/hoist or ric 	loade Identify drop zor				
	Mobile plant and equipment	rioada. Identity drop zor				
ш	 Ensure good comms between operator and safety observers. Check ground condition conduct pre-use checks. Work within safe working loads. Follow a lifting plan. 	ons.				
	Rotating plant, entanglement, mechanical hazards					
ш	 Observe wind speed limits. Apply mechanical isolations. Be aware of potential pinc 	h/crush hazards.				
	Hub entry—Be aware of risk of unexpected pitching in hub. Yaw lock—Isolate power to yaw motors at all times while yaw lock is in place.					
	 Yaw entry—Test E-stop in yaw space before any other work activity. If restoring yaw 	system while a person				
	in the yaw space, limited to visual inspection only.					
	Hydraulics Do not touch or keep your hands close to hoses or hydraulic fittings under pressure					
	 Release stored hydraulic energy before working on hydraulics. 					
	Safety glasses are required whenever you are working on hydraulics. Chemical hazards, spills					
Γ,	 Review SDS sheets for chemicals (oils, grease, etc). Use appropriate PPE (e.g. glor 	ves, mask). Use spill kits				
	ire hazards					
_	 Sweep and clean up all combustibles. Take extra care in dry/windy conditions. Che Hot work permit + fire watch required for hot work. Visual check of fire extinguishers 	ck rural fire hazard level report any defects				
	Electrical Supplies	report any acreate.				
_	 Isolate and de-energize, Lock and Tag, then Prove-Test-Prove before touch. 					
	Prescribed electrical work (PEW) Maintenance of electrical appliances. Construction or maintenance of works (i.e. fitti	or used for electricity generation				
	 Connection or disconnection of works, electrical installations, or appliances—other 					
	 Testing, certification, inspection, or supervision of the work described above. Only trained and competent personnel may perform prescribed electrical work. 					
	Arc Flash (turbine main breaker +A12-Q1, auxiliary breaker +A12-Q2)					
	 Where possible, operate main breaker from over 3.0 m away – Isolate turbine befor Otherwise wear arc-rated PPE (minimum 25 cal/cm² = Category 3) to operate main 					
	Work in 'At Risk Areas' (any space with hindrance to rescue, or which may potentially become a confined space)					
	Rescue plan. Work in pairs. Carry gas monitors.					
	Confined Space Entry Confined space entry permit + procedures. Confined space training. Rescue plan. U	lan ann monitore				
	Fault-related hazards	ose gas monitors.				
П.	 Consider whether the type of fault may result in special hazards. 					
_	 Yaw error—If there is a yaw error, watch out for possible sharp pieces or exposed v 	vires in the nacelle.				
П						
_						
_						
	Resources					
	tt task-related safety resources (PPE, safety equipment) and critical task-related too	IS.				
	eneral PPE, Working at Height equipment—As appropriate to the work task. ersonal LOTO equipment—As required.					
	irst aid kit—Bring one first aid kit into the turbine or to the work site.					
In	isulated and calibrated electrical tools, PPE—Used during safe electrical work					
	as monitor—Mandatory for confined space entry or when working on accumulators					
	eplacement kit for yaw gears or yaw motors – See work instruction for full li	SLOTTOOIS.				
• R	epiacement nation yan gears of yan motors. Oce work instruction for fair					
• R	epideoniciti (in yaw gedisor yaw motors - See work instruction to their					
• R	epiacement at for year gears of year motors of the work installed on the main					

JSA

WSSP

AWP (ROP)

WI

Worksite Safety Plan

Arc Flash (turbine main breaker +A12-Q1, auxiliary breaker +A12-Q2) Where possible, operate main breaker from over 3.0 m away – Isolate turbine before operating aux breaker. Otherwise wear arc-rated PPE (minimum 25 cal/cm² = Category 3) to operate main breaker or aux breaker.
Work in 'At Risk Areas' (any space with hindrance to rescue, or which may potentially become a confined space) Rescue plan. Work in pairs. Carry gas monitors.
Confined Space Entry Confined space entry permit + procedures. Confined space training. Rescue plan. Use gas monitors.
Fault-related hazards Consider whether the type of fault may result in special hazards. Yaw error—If there is a yaw error, watch out for possible sharp pieces or exposed wires in the nacelle.
□ Task-specific content is
highlighted in blue
C. Resources
List task-related safety resources (PPE, safety equipment) and critical task-related tools.
 General PPE, Working at Height equipment—As appropriate to the work task. Personal LOTO equipment—As required. First aid kit—Bring one first aid kit into the turbine or to the work site. Insulated and calibrated electrical tools, PPE—Used during safe electrical work procedures. Gas monitor—Mandatory for confined space entry or when working on accumulators in the hub. Replacement kit for yaw gears or yaw motors – See work instruction for full list of tools.
•

JSA

WSSP

AWP (ROP)

WI

Approved Written Procedure

- Safety checklist during the job
- Isolations and safety steps (only)
- Includes regulatory requirements, like pre-use checks

Routine Operating Procedure

- No isolations, just a few safety steps
- General work only

JSA

WSSP

AWP (ROP)

WI

Approved Written Procedure

		н	ub entry		
atmos	phere (e.g. fur	At Risk Area rules. If t	he task or working conditions accumulators) then use a diff		
Wind	Wind farm: Turbine #: White Hill Turbine type: Vestas V80–2.0MW wind turbine		Asset shutdown time:	Asset restart time:	
Turb			WTG Work Order #:		
1.0	Permit a	uthority—Sign o	n to AWP or transfer authority	to another	Technician
Auth	Authorised Technician name:		Sign on:	Date:	
2.0	Remove	from service			
2.1	If isolations are already in place, note Form 4005 number here.			Form 4000 serial number	
2.2	Request Transfer of Control—Confirm turbine restrictions				
2.3	Set Service/Remote Key to 'SERVICE'.		Signature	Time	
2.4	Set turbine to PAUSE—Remove key.				
2.5	Check windspeed (10 min average)—Windspeed:				
2.6	Turn OFF: top	assembly cooling, o	ffline oil filter, top ventilator.		
3.0	Service I	lift			
3.1	Turn ON: lift p	power supply.			
_	Perform pre-use checks for service lift.			_	

JSA

WSSP

AWP (ROP)

WI

Approved Written Procedure

	6.0	Apply hydraulic rotor locks			100	
	6.1	Stop the shaft/hub at appropriate angle—Set turbine to PAUSE. Pitch blades near 87° stop—Release/apply brake to align holes.				
	6.2	Apply hydraulic rotor locks Both pins extended—Handle in lock position—Apply Tag	Signature	Time		
	6.3	Pitch blades to 87° full stop position—Hit E-stop to apply brake. Later, reset E-stop/brake as required for the work task.				
ROMP	7.0	Restoration of Motive Power—hydraulic re	otor lo	cks	R	
	As rec	quired, temporarily remove isolations—Section R7.				
	8.0	Apply manual rotor lock (if required)				
	8.1	Apply manual rotor lock—Apply Tag	Signature	Time		
	8.2	Pitch blades to 87° full stop position—Hit E-stop to apply brake.				
	9.0	Enter hub				
	9.1	Discuss rescue plan—A rescue trained person remains nearby.				
	9.2	Push E-stop before entering hub. Later, reset E-stop as required				
	9.3	Apply isolation: Open all THREE blade leak valves (5V1). Drain pressure in pitch system—Apply Tags	Signature	Time:		
ROMP	10.0 Restoration of Motive Power—blade valves (5V1)					
ROMP	As required, temporarily remove isolations—Section R10.					
ROMP	As rec	juired, temporarily remove isolations—Section R10.				
ROMP		D Perform work in the hub				

JSA

WSSP

AWP (ROP)

WI

Work instructions

- How to actually do the job
- Also charts, diagrams, other notes
- Keep this information out of the other formal documentation
- Encourage techs to help build up this body of IP.

JSA

WSSP

AWP (ROP)

WI

Work instructions

- N.11 Reset E-stop on chain hoist pendant controller.
 - Operate the chain block using the pendant controller.
 - Before lowering the chain to the ground, test the pendant control buttons for down, up and stop.

If the 'up' control is malfunctioning, then it is too late to discover this when 70m of chain has already been lowered to the ground.



N 12 After use:

- Switch off socket and unplug before putting away chain hoist.
- After use, place the chain block and the crane in their holders.
- Park the crane so that it is supported when hydraulic pressure is released.
- Ensure that the hoist cables are unplugged and put away tidy and not tangled.



N.13 • Note that the chain hoist cannot sustain constant use at full load.

 If you are transferring multiple heavy loads from ground level to the nacelle, allow the chain hoist to rest and cool down for a few minutes between loads.


JSA

WSSP

AWP (ROP)

WI

Work instructions



JSA

Plus:

WSSP

 Meridian's WTSR Rules (our booklet of the actual rules)


AWP (ROP)


 Management Instructions (guidance for odd situations)

WI

Paperwork







"Basic permit competency"

Trained in:

- safe turbine operation
- isolations
- boundaries of work

Routine Operating Procedure (general work, no isolations)

"Advanced permit competency"

Demonstrated competency in:

- the WTSR rules
- How to handle situations where the rules break down

Approved Written Procedure (apply LOTO isolations)

...this is NOT technical competency



You'll know it when you see it.

But what about...

 Doesn't having a script of isolations dumb it down?

But what about...

 Doesn't having a script of isolations dumb it down?

NO!





You'll know it when you see it.

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?

Then the job waits

We've got people working on it...



You'll know it when you see it.

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?
- What if, mid-job, I see something else to fix?
 Do I just leave it?

YES

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?
- What if, mid-job, I see something else to fix?
 Do I just leave it?

If it's dangerous, lock it out.
Otherwise, just raise a new work order.



You'll know it when you see it.

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?
- What if, mid-job, I see something else to fix?
 Do I just leave it?
- Isn't this less efficient?

YES (we know)

But what about...

- Doesn't having a script of isolations dumb it down?
- What if there's no AWP written for this job yet?
- What if, mid-job, I see something else to fix?
 Do I just leave it?
- Isn't this less efficient?

Our framework: Wind Turbine Safety Rules

To achieve Safety From The System:

- 1. all work in the turbine is **planned work**...
- 2. following an Approved Written Procedure...
- 3. which lists approved isolations and safety steps.

The primary goal is technician safety

Evolution of a Safety Culture (Safety-II)

Focus on systems

SAFETY CULTURE

Focus on technicians



Teach away the errors

SUPPORT the Techs Stop counting errors and attributing blame!

Fix the systems and manage the problems



Thanks!